

United States Department of the Interior

GEOLOGICAL SURVEY

GPO Box 4424 1986 MA San Juan, Puerto Rico 00936

1986 MAY 27 PH 1: 51

CARIBBEAN FILED OFFICE SANTURCE PUERTO RICO CO ST.

Mr. Pedro A. Gelabert, Director
U.S. Environmental Protection Agency
Caribbean Field Office
1413 Fernández Juncos Ave.
Santurce, Puerto Rico 00909

File: Garrochules LF Camb

Dear Mr. Gelabert:

The following are review comments concerning the water aspects of the "Preliminary Site Inspection Report" of the Garrochales landfill near Arecibo, P.R.

Arecibo Londfill

- 1. The sampling from the two wells located 2.25 miles upgradient (southwest of the landfield area) cannot be used as criteria to evaluate the potential for ground-water contamination due to the landfield.
- 2. According to the report "Restoration of Freshwater in the Caño Tiburones Area, Puerto Rico" (USGS WRI 83-4071), the top of the Aymamón aquifer is about 70 feet below land surface at the southern part of Caño Tiburones and not 200 feet as established in the subject site inspection report.

Cordially,

Ferdinand Quiñones Chief, Caribbean District Water Resources Division

FQ/zd